The low walls on the Green create three rather isolated spaces, diluting its coherence and inhibiting free movement throughout the space.

Some access points to and from the Green are not well

 The station buildings, although not unattractive, are somewhat shabby and the interface between the station and its environs is weak and poorly defined.

The children's playground is very hard in appearance with no planting or vegetation.

The large advertisement hoardings affixed at high level to the gable at no. 33 and in front of no. 9 Lower Richmond Road are eyesores and present a poor image at this entry point into Mortlake.

Jolly Milkman pub, Lower Richmond Road is an eyesore due to its derelict state. The ground floor extension to 39 Lower Richmond Road

containing an office is an eyesore.

The disused but visually interesting social club opposite the

1 AP Memories of Mortlake and

No. 43 Queen's Road

 The small water tower to the rear of Rosemary Gardens is in poor condition.

• The blocks of flats either end of Rosemary Gardens detract from the character of the Almshouses because of their appearance and scale. The rear elevations are particularly poor.

Front boundaries to Waldeck Terrace have been weakened and a few houses have lost their original

 A number of chimney pots to ornate stacks on Rosemary Gardens have been lost.

## Queen's Road - Problems and pressures

The heavy use of the highway and footway for parking has diminished the quality of the tight knit pattern of roads, the vehicles distorting the proportion of the vista and distracting attention away from the buildings. Well intentioned but often unsympathetic and inappropriate home 'improvements' have in a number of cases seriously damaged the simple form of buildings.

Narrow roads and high levels of car ownership result in the dominance of parked vehicles over pedestrian

 The recreational potential of the cemetery is not fully Poor boundary treatment to railway line and bridges in


need of redecoration. Ill considered alterations to many of the houses.


Derelict site on the northern end of Rock Avenue requires

 The tarmac path fronting Rock Avenue could benefit from an appropriate gravel dressing to complement the surviving


Some adjoining areas are now considered of sufficient character to justify conservation area status.

The use of asphalt as a paving material in Queen's Road is out of character.






This map outlines the key problems & pressures and provides an urban design analysis of the conservation areas







Public Open Space (towpath only - see also UDP inset



Conservation area boundary





Linear green space which would benefit from environmental improvements or better maintenance




Local landmarks (including those shown on UDP inset


Centres of activity















Community severance

 ── ── Key links to River Thames

tural quality

Community edge

Note: for clarity, key tree groups are shown on the I oposals Map

------

Strong gateway/entry point

Area under environmental or townscape stress due to

parking or traffic levels and or intensity/conflict of uses

Buildings with positive tow iscape frontage/good surveil-

Landscaped areas/open space which would benefit from

Significant buildings of poo /neutral townscape/architec-

Frontages/corridors with poor surveillance/lack of



